

OHSC OCTOBER 2024
TRAIL MAINTENANCE PHOTOS



Denny Manner used the brush hog several days covering only a couple miles a day. Part of the slowness is due to bumpy trail, which makes the cutter bounce and cut unevenly.



Chris attaches an ORV sign.



Attaching signs



The new carsonite ORV post signs show we are designated.



Lots of bumps and soft sand dust on Trail 9.



Skip pounds in a carsonite ORV post.



Mark unloads the 3-pt. hitch that came off the R tractor so he can make another one for the new tractor we are getting.



Mike headed out Wednesday with brush hog to mow the shoulders.

Replacing signs



The carsonite post pounder gets heavy after a while.



Denny had to deal with stutter bumps and dust when he brushing trail 9 at 3 mph.



You have to be tall to get the post pounder off the carsonite posts.



Dan using the Dubie cutter on East 6



John, Don, Greg can't decide which way to go.





The drag broke out on the trail with Mike driving. Greg called Dan White, who was out with the Dubie sickle. Fortunately some hunters came by and helped cut a log to put between the axle. Dan used the bucket to lift the log and chain it to the frame so Mike could hobble the rig back to the barn.







Tom moved a bunch of trees off the trail. Dan dropped leaners and other brush from the side of the trail earlier.



Tom Barron found lots of brush on the trail.



Back in the barn, John welded the drag back together and cut out the log.





Mike looks at the bent bar from the Dubie sickle which needs to be straightened out.



The brush hog also needed some work.



Bryan and Pam spent the weekend at the show.



One of our Club sponsors was across the aisle from us.



Bryan's line up of SkiDoo's.

Two "Michigan" antiques



Gary, Skip worked Saturday – Bryan and Pam (who took the picture) were there all 3 days.